

Contents

Safety	•••••••••••••••••••••••••••••••••••••••	1
Package	e Contents	1
Unpack:	ing	1
Instal	lation	2
1.	Environment Required	2
2.	Install Spectrophotometer	2
Overvie	ew	2
Symbols	s	3
Main S	pecifications	3
Descri	ption of Appearance and Keys	4
1.	Appearance	4
2.	Keypad	5
3.	Description of Keys	5
Functio	ons	6
Getting	g Started	6
Importa	ant Guidelines	7
Genera:	1 Operating	7
Measur	ing	8
1.	Photometry	8
2.	Quantitation	9
3.	Utility	9
Trouble	eshooting	15
Repair	and Maintenance	16
1.	Daily Maintain	16
2.	Spare Parts Replacement	16

arranty	Warranty
quipment Disposal	Equipment

Safety

Please follow the guidelines below, and read this manual in its entirety to ensure safe operation of the unit.

We recommends against the use of SP-UV1000 Spectrophotometer.



- Do not open the device.
- Disconnect the device from the mains supply before carrying out maintenance work or changing the fuses.
- The inside of the device is a high-voltage area Danger!
- Do not use the device if it is damaged, especially if the main power cable is in any way damaged or defective.
- Repairs may only be carried out by the service technicians fromus and authorized contractual partners.
- The device must be connected to a power outlet that has a protective ground connection.
- If the equipment is used in a manner not specified by the manufacturer, the protection provided by the equipment may be impaired.



- Do not allow any liquid to enter into the device.
- Do not operate the device in a hazardous location or potentially explosive environment.

Package Contents

Description	Quantity
Spectrophotometer	1PC
10mm Glass Cuvette	4PCS
10mm QuartzCuvette	2PCS
Power Cord	1PC
User's Manual	1PC
Dust Cover	1PC

Unpacking

Open the package, according to carefully check the packaging packing list items, if found inside the packaging are missing or damaged items please

contactus and authorized contractual partners.

Installation

1. Environment Required

To ensure the best performance, the following conditions are required:

- The best working temperature range is 16-35 °C and the humidity is 45-80%.
- Keep it as far as possible away from the strong magnetic or electrical fields or any electrical device that may generate high-frequency fields.
- Set the unit up in an area that is free of dust, corrosive gases and strong vibrations.
- Remove any obstructions or materials that could hinder the flow of air under and around the instrument.
- The power requirement is $110\pm11V/60\pm1Hz$ or $220\pm22V/50\pm1Hz$.
- Use the appropriate power cord and plug into a grounded outlet.
- If the local voltage is not stable, a voltage regulator is required.
- Be away from direct sunlight.

2. Install Spectrophotometer

Placement

Place the instrument on the stable table carefully.

Install Printer (Printer is Optional Accessories)

Check to confirm instrument power switch is turned off, connect the printer's data cable to the instrument's parallel port.

Link the Power Cord

Check to confirm instrument power switch is turned off, the power cord plug into two separate power interface and power supply socket apparatus.


Overview

SP-UV1000 Spectrophotometer is an electrical measure instrument which is widely used in the laboratories.

•	Use Frequency:	Intermittence
•	Excessive Voltage(Current):	No
	Pollution Class:	Class 1

Symbols

The following chart is an illustrated glossary of the symbols that are used in this manual.





Recycle, this instrument will be called back by the appointed Electrical Treatment Department or by the original Manufacturer when wasted.

Main Specifications


•	Optical System	Single beam
•	Wavelength Range	200—1000nm
•	Wavelength Accuracy	±2nm
•	Wavelength Repeatability	0.8nm
•	Photometric Range	-0.3—3A, 0—200%T
•	Photometric Accuracy	±0.5%T
•	Photometric Repeatability	0.3%T
•	Spectral Bandwidth	4nm
•	Stray Light	0.3%T@220nm&360nm
•	Stability	±0.002A/h@500nm
•	Work Mode	Photometry, Quantitation
•	Interface	USB, Parallel(printer)
•	Power Requirement	AC 110/220V, 50/60Hz

•	Dimensions	490x360x210
•	Weight	14kg
•	Work Environment	15 $-$ 35 $℃$,15 $-$ 70% relative humidity
•	StoreEnvironment	-10 $-$ 50 $^\circ \!$

Description of Appearance and Keys

1. Appearance

Front View



Back View




- 1 LCD Display
- 2 Keypad
- 3 Lid of Sample Room
- 4 Rod
- 5 LCD Contrast Adjust
- 6 Printer port

- 7 USB port
- 8 Cover of Fan
- 9 Power Socket
- 10 Power Switch
- 11 Cover of Cooling Vents

2.Keypad



3. Description of Keys





Function Key: Functions according to the screen

 $\bigtriangleup \bigtriangledown$

UP, DOWN Keys: Scroll menu/data and set Y scale

Functions

Photometry
Display results as Abs, %T or Energy.

Quantitation Use a Standard Sample to establish Standard Curve.

Getting Started

The following chart describes the basic operation of the instrument.


Turn On and Self-check

Switch on the power. Then the instrument begins to self-check and 20 minutes' warm up. Self-check includes the following steps:Turn on lamps \rightarrow Check Sensor \rightarrow Initialize AD \rightarrow System position \rightarrow Get Dark Current \rightarrow Warm up.

Self-test...

Warm up 20 minutes, Any key to skip

After warm up, instrument displays Main Interface.



Important Guidelines

- Reagents and dilution buffers can cause cauterization and other damage to health.
- Samples (nucleic acids, proteins, bacteria cultures) can be infectious and cause serious damage to health.
- During sample preparation, measuring procedures and maintenance and cleaning work, observe all local laboratory safety precautions (e.g. wear protective clothing and gloves, use of disinfectant) regarding the handling of sample material.
- Dispose of measuring solutions and cleaning and disinfectant materials in accordance with the relevant local laboratory regulations.

General Operating

Select Application

Main interface, press the key (left) to enter into.

Set Wavelength

Test	interface,	press	key	GOTOK	o set	wavelength,	\bigtriangleup),	\bigtriangledown	to	modify

wavelength value, then press key (left) to go to wavelength and blank.

WL: 500.0nm
Please enter WL.:
500.0 nm
OK

Set Parameters

Press	SET enter	into setup	interface,	\bigtriangleup ,	to	select	items	or
input	parameters,	(left) to confir	m.				

Delete the test result and stored data

Test	Interface,	press	the	key ^{PRNT} ,	then press	key	\bigtriangleup	,	\bigtriangledown	to	select
		-		1 ,	Ŧ	-		<i>'</i>			

"Clear Data, not Print ", (left)to delete.

Blank

Put the Reference in the light path, press ZERO to do blank.

Measure Samples

Put the samples in the light path, press (left) to measure.

Print the test results

Test	Interface	, press the	key	PRINT	, 🛆 ,	\bigtriangledown	select	"Print,	clear
data'	', press th	ne key 🦳] _{(left}	t) to j	print.				

Store the Standard Curve

After	got	the	Standard	Curve	by Marked,	press	,	\bigtriangledown	input	the	file
name	and	pres	s — (1	eft) t	o save.						

Load the Standard Curve

"Quantitative"	interface,	press), 🔽) to select	"Load Curve	", press
	choose the	curve you	want,	press 🦳	(left) to	open.

Measuring


1. Photometry

Step 1. StartPhotometry

MainInterface, press key (left) to choose "Basic".

WL: 5	00.0nm	0.000A	WL:	50	0.0nm	0.000A
	100.09	%Т	No.	WL	%T	Abs.
Basic	Quant	tative	Tes	t		Cancel

Step 2. Set Wavelength



Step 3. Blank

Put the Reference in the light path and press ZERO to do blank.

Step 4. Measuresamples

Put the sample in the light path, and then the result displays on the


screen automatically, press (left) to record.

WL:	500.	Onm	0.000A
No.	WL	% T	Abs.
1	500.0	100.0	0.000
2	500.0	100.0	0.000
Tes	t		Cancel


2. Quantitation

Step 1. Start Quantitation

Main Interface, press key (left) to choose "Quantitative".




Step 2. Establishor call Standard Curve



2 methods to establish Standard Curve:


Method 1: Establish Standard Curve by inputting coefficients

1) Starts establish.Press , to select "Coefficient" , then



Method 2: Establish Standard Curve by using Standard Samples

1) Starts establish.Press , to select "Standard Curve", then press (left).




2) Set Wavelength.Press to enter to set wavelength, Press ,

to input wavelength value, press (left) to go the setting value.


- 3) Blank. Put the Reference in the light path, press ((left) to do blank.
- 4) Setup number of Standard Samples.Press , toinput the quantity of standard sample(No more than 9 standard curve.), press

(left) to confirm.




5) Calibrate Standard Samples. Put the corresponding standard samples

in the light path as the screen indicates, press, to input the concentration, press (left) to confirm, to finish all the standard samples.



Load the Stored Curve

Press, 🔽 to choose "Load Curve", press, 🔽 to cho	ose
the curve, press (left)to confirm.	




Press (left)to enter the test mode after building or loading standard curve.

Step 3. Enterinto MeasuringInterface

Press

└ (left)to enter into the QuantitationMeasuringInterface.



Step 4. Blank

Put the Reference in the light path, press ZERO to do blank.

Step 5. Measure Samples

500	. Onm	0	.000A
No.	WL	Abs	Conc.
1	500.0	0.039	0.078
2	500.0	0.042	0.084
3	500.0	0.041	0.082


3.Utility

Main Interface, press [SET] to go into utility setting.


WL: 500.0nm 0.000A	● Test Mode	
100.0%T	O D2 Lamp	0n
100.0%1	O W Lamp	0n
Basic Quantitative	ОК	Cancel

Test Mode

Press	△, (Vto	choose	"Test	Mode",	press -	- (left)	toe	enter,	press
二、		to choos	e "Abs"	, "%T″	, "Energ	y", press	, <u> </u>	eft)	to con	firm.




Turn On/Off D2 Lamp Press, , then press (left) to enter into.Press, , o choose "On" or "Off", press (left) to turn on/off.



Turn On/Off W Lamp


Press, , then press (left) to enter
into.Press, 🔽 to choose "On" or "Off", press — (left) to turn
on/off.



Get Dark Current

Keep the light path without anything blocking, press , to choose "Dark Current", then press (left) to resample Dark Current.

Note: During the course, open the lid of the compartment is prohibited.



Reset Wavelength


K	eep the light path without anythi	ng blo	cking, pro		, 🔽	Jto choos	e
"]	Reset WL", then press () to r	eset wave	length.			
	O Dark Current						
	⊙ Reset WL		0 1 1	. •	117 T		

C	Reper und		Calibrating	WI
0	Version		Caribrating	WL2 •
OK		Cancel		

About Version

(

Press, Version", press (left) to view version
information, press any key to return.	



Troubleshooting

Review the information in the table below to troubleshoot operating problems.

Problem	Cause	Solution
Power on, no response	Power cord connection is	Improve connectivity
	not reliable	
	Fuse burning	Replace fuse
Measurement uncertainty	Warm up is not enough	Warm up more time
	Sample is not Stable	Improve the sample
	The concentration of	Diluted sample
	sample is too high	
	Power Supply Voltage Low	Improve the Power Supply
	or not Stable	
	Lamp damage or lamp life	Replace lamp
	maturity	
Dark Current Error when self-check	The lid of the	
	compartment is open	Close the lid, restart
	during self-check	
System Calibrate Failed	Something block the	Remove it, calibrate
	Light path	again
Power on, back light is	Display Contrast problem	Adjust the contrast potentiometer
OK, but nothing display		
on the screen or display		
is not clear		
Measurements inaccurate	Cuvettes were	Clean cuvettes
	contaminated	
	Samples were	Improve samples
	contaminated	
	Worse matching of the	Improve the matching of
	cuvettes	the cuvettes
	Dark current error	Resample dark current

Repair and Maintenance

1. Daily Maintain

Check the Compartment

After measurement, the cuvettes with sample solutions should be taken out of the compartment in time. Or the volatilization of the solution would make the mirror go moldy. Users must pay more attention to the corrosive sample and liquid easy to volatilize. Any solution remains in the compartment should be wiped off immediately.

Surface Clean

The cover of the instrument is with paint. Please use wet towel to wipe off the drips on the surface immediately. Organic solution is forbidden to be used to clean the cover. Please wipe off the dirt on the cover timely.

Clean the Cuvettes

After every test or after a solution change, the cuvettes should be cleaned carefully, or the remains on the surface would cause measuring error.

2. Spare Parts Replacement

Replace the Fuse




Danger! Be sure to switch off the power and unplug the socket before replacement!

- Step 1. Tools preparation
 Prepare a 3×75 Flat Blade screwdriver.
- Step 2. Switch Off the power supply
 Switch off the power supply, and unplug the socket.


Step 3. Take out the Fuse Seat

Take out the fuse seat by the screwdriver.



Step 4. Replace a new fuse

Pick out the spare fuse (3.15A/250V) and replace it to the working position.



Step 5. Reset the fuse seat

Replace the fuse seat in the power socket.

Step 6. Switch on the power

Plug the socket and switch on the power.

Replace Lamps



Hot! Wait 20 minutes before open the lamp chamber after power off to avoid scald!

Step 1. Tools preparation

Prepare a 6×150mm Cross Blade screwdriver and a pair of glove.

Step 2. Power Off


Switch off the power supply and unplug the socket.

Step 3. Open the cover

Unscrew the 4 screws indicated(Each side with 2 screws) and remove the cover.



Step 4. Open the cover of the light chamber Unscrew the 2 screws on the light chamber cover and remove it.



Step 5. Replace the D2 lamp


Unscrew the 2 screws on the D2 Flange (No.1), unplug the connector in the Power Board (No. 2)and remove the D2 lamp. Draw on the cotton glove and replace a new lamp. Fix the 2 screws and plug the connector again.



Step 6. Replace W lamp


Pull out the defected W lamp and draw on the cotton glove. Insert the new W lamp as deep as possible on the lamp seat. Be sure to keep the

filament in the same direction as the old one face.



Adjust the position of the W lamp

Switch on the power(the Switch Mirror should be placed to the position asindicates). Observe the entrance facular, and it should in the center of the entrance hole. If the facular deviate to Left or Right, then loosen the No.1 screws in Fig. 5-8 and move the lamp seat to Left or Right until it focus on the center of the slot. Then fix the screws. If the facular deviate to Up and Down, then loosen the No.2 screws and move the lamp seat Up and Down until the facular focus on the center of the slot. Then fix the No. 2 screws again.



Step 7. Finish

Reset the cover of the light chamber and fix the screws. Reset the cover of the instrument and fix the screws. Recover the Pole in the

compartment, then the course finished.

Warranty

Wewarrant that this product will be free from defects in material and workmanship for a period of one (1) year from date of purchase. If a defect is present, we will, at its option, repair, replace, or refund the purchase price of this product at no charge to you, provided it is returned during the warranty period. This warranty does not apply if the product has been damaged by accident, abuse, misuse, or misapplication, or from ordinary wear and tear.

For your protection, items being returned must be insured against possible damage or loss. This warranty shall be limited to the replacement of defective products. IT IS EXPRESSLY AGREED THAT THIS WARRANTY WILL BE IN LIEU OF ALL WARRANTIES OF FITNESS AND IN LIEU OF THE WARRANTY OF MERCHANTABILITY.

Equipment Disposal



This equipment is marked with the crossed out wheeled bin symbol to indicate that this equipment must not be disposed of with unsorted waste.

Instead it's your responsibility to correctly dispose of your equipment at lifecycle -end by handling it over to an authorized facility for separate collection and recycling. It's also your responsibility to decontaminate the equipment in case of biological, chemical and/or radiological contamination, so as to protect from health hazards the persons involved in the disposal and recycling of the equipment.

For more information about where you can drop off your waste of equipment, please contact your local dealer from whom you originally purchased this

equipment.

By doing so, you will help to conserve natural and environmental resources and you will ensure that your equipment is recycled in a manner that protects human health.

Thank you!



DLAB Scientific Inc.

Suite R, 5308 Derry Avenue, Agoura Hills, CA91301 California, United States. Tel: +1-909-742-8958 Fax: +1-909-939-4212 Sales contact: <u>info@dlabsci.com</u> Service contact: <u>dlabusa@dlabsci.com</u> www.dlabsci.com